

FOBAS Bulletin



17th August 2020

Off-Specification Fuels from Zona Comun, Argentina

In the last week, FOBAS has tested a number of samples from Zona Comun which were ordered as ISO-F-RMG380 grades, that exceeded the ISO 8217 specification limit of 0.50 % v/v for water content. The water values tested were in the range 0.85 % v/v – 2.00 % v/v. Ash and metals analysis results suggest the water to be fresh water and not saline/sea water.

Water at these levels would generally be expected to be manageable with effective onboard treatment including efficient purification, however is still be a concern and would also have commercial implications interms of quantity of fuel received.

If high water is found in a bunker fuel then further samples should be taken from the top, middle and bottom of the respective bunker tank(s) to determine the distribution of water through the tank. Further to this, samples can be taken from before and after the purifier as well as engine entry to determine the reduction of water to acceptable levels (0.20%v/vv) before engine entry.

Any carry over of water into the engine fuel rail can cause possible damage to the fuel pumps, injectors and cylinder components as well as possible turbo charger surging and fouling.

If your ships are planning to bunker in this port then we suggest that the supplier is asked to provide a certificate of quality of the particular stem to ensure that the water concentration is known at the time of bunkering and within the limits of stipulated grade. Particular attention should be given to the collection of a fully representative drip samples ensuring all supporting documentation and samples drawn are witnessed and signed for by all parties present.

If you require any further information about this Bulletin, please contact us at fobas@lr.org or speak to one of our consultants on +44 (0)330 414 1000 (Southampton UK), +44 (0)1642 440991 Redcar (UK), +65 3163 0888 (Singapore), +30 211 990 7732 (Greece). For anything urgent, please contact us via our out of office number, +44 (0)1642 425660.

Copyright © 2020 Lloyd's Register Group Services Limited. All rights reserved.

Lloyd's Register Group Limited, its subsidiaries and affiliates and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.